




GREEN MACHINE™

CHARGE OUTLET INSTALLATION



If the Green Machine requires a 220/240V, 50A circuit for charging, install an outlet using a CS6369 receptacle as shown in the diagram above. The neutral wire (W) is not needed by the Green Machine charger and can be left not connected. The neutral wire can be connected if needed for other equipment - it will not affect the Green Machine equipment.

